Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5060**

Resource Identification

Property Name(s): ..... Warren House (owner plans to demolish) {Current}
Property Date: ..... ca 1880
Address(s): ..... 13434 Old Suffolk Road {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Component Description:

Component	Comp Type/Form	Material	Material Treatment
Foundation	Foundation - Piers	Brick	Foundation - Common Bond
Porch	Porch - 1-story, 3-bay	Wood	Porch - Post,Turned,Bracketed
Roof	Roof - Gable, Side	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Double-hung	Wood	Windows - 6/6
Chimneys	Chimneys - Exterior side	Brick	Chimneys - Common Bond
Chimneys	Chimneys - Central interior	Brick	Chimneys - Common Bond

Site Description: ..... This house is located in a rural area of Isle of Wight County. This house is currently vacant and Mrs. Warren, the woman that owns the house, lives in a modern house to the south.

Secondary Resource Desc: Two outbuildings are associated with this house.

WUZIT Count:

No.	Wuzit Types	Historic?
1	Garage	Non-historic
1	Shed	Non-historic
1	House	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5060**

Individual Resource Information

WUZIT: Shed

Est. Date of Construction: 1970 ca {Owner/site visit} *Accessed?* No
Primary Resource? No *Number of Stories:* 1.0
Architectural Style: Other *Condition:* Good
Interior Plan Type: *Threats to Resource:* Transportation Expansion
Description: To the southeast of the house is a shed constructed of the same materials as the garage.

WUZIT: Garage

Est. Date of Construction: 1970 ca {Owner/site visit} *Accessed?* No
Primary Resource? No *Number of Stories:* 1.0
Architectural Style: Other *Condition:* Good
Interior Plan Type: *Threats to Resource:* Transportation Expansion
Description: East of the house is a garage covered in vertical wood paneling with a gabled roof clad in composition shingles.

WUZIT: House

Est. Date of Construction: 1880 ca {Owner/site visit} *Accessed?* No
Primary Resource? Yes *Number of Stories:* 1.0
Architectural Style: Other *Condition:* Good
Interior Plan Type: *Threats to Resource:* Transportation Expansion
Description: Built c. 1880, this one-story Frame Vernacular style house may also be considered Folk Victorian in style. This house features a wooden frame structural system that rests on brick piers. The exterior is covered in weatherboard and the gabled roof is clad in standing-seam metal. There are four brick chimneys associated with this house. A chimney is located at each exterior end of the house, one is in the central interior portion of the rear-gabled addition, and the fourth chimney is situated on the interior portion of the back porch. Fenestration consists of six-over-six wooden double-hung sash windows and several one-by-one sliding windows. Some of the windows feature decorative shutters. The front porch spans the entire width of the house and features a shed roof that is supported by turned wooden posts. Other exterior ornamentation includes gable end returns, decorative brackets under the eaves, and wooden window surrounds.

Cemetery Information

Bridge Information

National Register Eligibility Information (*Intensive Level Survey*)

Historic Context(s): Domestic

Historic Time Period(s): P- Reconstruction and Growth (1865 to 1914)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:* 046-5060**

Reference #: 1
Bibliographic RecordType: ..... Survey
Author: ..... CCR, Inc.
Citation Abbreviation: .....
Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	5	VDHR	2004/07/01	Single Dwelling

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: .. .... Phase I Survey
Date: 2004/08/31
Organization or Person: ..... CCR, Inc.
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2,
Cultural Resource Management Event: ..... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: ....
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: ....